

Wrap a sanding block with 2000 grit sand

4.


Spray water onto damage



When sanding, make sure the damaged area is always wet by spraying water onto the area.

5.

Sand surface



Rub surface area gently with the sandpaper. Make sure the area is always well lubricated with water. The scratch is no longer visible.

Note: be careful not to rub too hard and remove the clear coat. If you do this, you will remove the clear coat.

6.

Wipe area



Regularly wipe down and check the level of the clear coat. The difference is noticeable.