



Use pre-prep cleaner to clean the surface in preparation for the repair. This will return the surface back to its raw condition.

4.

Mask out non metallics



Mask out non-metallic area and areas that do not require painting.

Example: if 2 different colours are used, mask out non-metallic area and areas that do not require painting.

5.

Paint metallics



Colour match paint to the metallic surface.

You may need to mix a little of black paint to get the right colour as there are many shades of metallic silver such as; a gold tint (add black paint).

Test your colour by spraying a small area of the metallic surface.